

BACKGROUND:

A crane crew has attempted to lift a gas bottle trolley, when the lifting attachment assembly on the trolley has failed. No one was injured but could have had catastrophic consequences. The company that purchased the trolley has begun an investigation into the incident.

RECOMMENDATIONS:

1. All lifting attachments on gas bottle trolleys should be inspected regularly for signs of fatigue.
2. Ensure that all trolleys or any other lifting attachments meet AS1418 and come with engineering certificate at point of purchase.

SAFETY ALERT



For further information contact Steve McCann:
Mob: 0488 102 297
Email: smccann@cfmeuwa.com